

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Fig. 1 PRIOR ART




Fig. 2

- 101, 201, 301 -
first cell disassembling section
102, 202, 302 -
second cell disassembling section
103, 203, 303 - decoder
104, 204, 304 - multiplexer
105, 205, 305 - signal generator
106, 206, 306 - address indicator
107, 207, 307 - controller
108, 208, 308 - detector
109, 209, 309 -
second cell assembling section
110, 210, 310 - selector
111, 211, 311 - coder
112, 212, 312 -
first cell assembling section




Fig. 3




Fig. 4

ADDRESS	bs1	bv1	bs2	bv2	bs3	bv3
DESTINATION	CLD 101	CLD 102	CLD 201	CLD 202	CLD 301	CLD 302

Fig. 5

DETECTION SIGNAL	NOTHING	SYNCHRONOUS SIGNAL 116	SYNCHRONOUS SIGNAL 216	SYNCHRONOUS SIGNAL 316
ADDRESS SIGNAL	av1	av1	av2	cv1

Fig. 6

DETECTION SIGNAL	NOTHING	SYNCHRONOUS SIGNAL 116	SYNCHRONOUS SIGNAL 216	SYNCHRONOUS SIGNAL 316
ADDRESS SIGNAL	av2	av1	av2	cv1

Fig. 7

DETECTION SIGNAL	NOTHING	SYNCHRONOUS SIGNAL 116	SYNCHRONOUS SIGNAL 216	SYNCHRONOUS SIGNAL 316
ADDRESS SIGNAL	bv1	av1	av2	cv1